

**COON CREEK WATERSHED DISTRICT  
Request for Board Action**

**MEETING DATE:** January 27, 2025  
**AGENDA NUMBER:** 14  
**ITEM:** Ditch 37 Inspection Report

---

**POLICY IMPACT:** Policy  
**FISCAL IMPACT:** Budgeted

---

**REQUEST**

Receive inspection report.

**BACKGROUND**

This inspection is part of the District’s Operations and Maintenance (O&M) program and the National Pollutant Discharge Elimination System (NPDES) requirement of inspecting 20% of the open channels annually.

Ditch 37 is located in Andover.  
 The channel is 4.17 miles (22,018 feet)  
 Drainage area is 3.5 square miles (2,239.5 acres)  
 0 Public Laterals



**IDENTIFIED MAINTENANCE NEEDS**

<b>Need</b>	<b>Count</b>	<b>Cost Estimate</b>	<b>Immediate</b>	<b>Repair</b>	<b>Monitor</b>
Obstruction	12	\$22,000	\$0	\$6,000	\$16,000
Ditch Repair	4	\$48,367	\$0	\$0	\$48,367
Bank Failure	7	\$28,715	\$0	\$0	\$28,715
Illicit Discharge	5	\$0	\$0	\$0	\$0
Beaver	0	\$0	\$0	\$0	\$0
Other	13	\$0	\$0	\$0	\$0
	<b>41</b>	<b>\$99,082</b>	<b>\$0</b>	<b>\$6,000</b>	<b>\$93,082</b>

**RECOMMENDATION**

1. Receive report.

# Ditch 37 General



-  Private Ditch
-  Public Ditch
-  Roads
-  Subwatershed
-  CCWD Boundary
-  ANDOVER
-  Immediate Repair
-  Maintenance Req.
-  Monitor
-  No Problem

